

MANUFACTURER: DATE PREPARED:

Western Excelsior Corporation P.O. Box 659 90 1 Grand Avenue Mancos, CO 81328 (970-533-7412) 06/01/2011

## MATERIAL SAFETY DATA SHEET

PRODUCT NAME: EXCEL R-1

WOOD FIBER EXCELSIOR, SINGLE NET TEMPORARY EROSION CONTROL BLANKET

CHEMICAL FAMILY: CAS. NO. 8003-70-0 POLYETHYLENE & ORGANIC

OSHA HAZARD: NO

DESCRIPTION: MACHINE PRODUCED MAT OF CURLED ASPEN

WOOD EXCELSIOR WITH EXTRUDED

POLYPROPYLENE NET ON TOP OF MAT, NET

SEALED TO EXCELSIOR FIBER WITH

CONTINUOUS LINES OF POLYETHYLENE THREAD

### CAUTION: MOLTEN MATERIAL WILL PRODUCE THERMAL BURNS

## PHYSICAL DATA

APPEARANCE & ODOR: WOOD EXCELSIOR FIBER, EXTRUDED PLASTIC

MESH & POLYPROPYLENE AND/OR POLYETHELYNE THREAD. MILD ODOR

SOLUBILITY IN WATER: NEGLIGILBE

MELTING POINT: 285 – 300 DEGREES F

SPECIFIC GRAVITY: VARIABLE (DEPENDANT ON MOISTURE

CONTENT)

% VOLATILE BY VOLUME: N/A

PH: 5

## FIRE AND EXPLOSION DATA

FLASH POINT: > 600 DEGREES F

AUTOIGNITION > 400 - 500 DEGREES F

TEMPERATURE:

EXPLOSIVE LIMITS IN AIR: N/A

EXTINGUISHING MEDIA: WATER SPRAY, DRY CHEMICAL

SPECIAL FIRE FIGHTING SPRAY WITH WATER. WEAR SCBA AND

PROCEDURES: PROTECTIVE CLOTHING TO PREVENT

CONTACT WITH SKIN

UNUSUAL FIRE & STRONG TO SEVERE (if blanket comes in

EXPLOSION HAZARDS: contact with ignition source)

### **REACTIVITY DATA**

STABILITY: STABLE

INCOMPATIBILITY: AVOID CONTACT WITH OXIDIZING AGENTS,

DRYING OILS, FLAME, TEMPERATLTRES OVER

400 DEGREES F

POLYMERIZATION: WILL NOT OCCUR

HAZARDOUS COMBUSTION WILL PRODUCE CARBON

DECOMPOSITION DIOXIDE, CARBON MONOXIDE, ALDEHYDES,

PRODUCTS: & INORGANIC ACIDS.

### **HEALTH HAZARDS**

EXPOSURE LIMITS: N/A

EYE CONTACT: NO SPECIFIC HAZARD

SKIN CONTACT: MOLTEN MATERIAL WILL PRODUCE THERMAL

**BURNS** 

INGESTION: LOW HAZARD

INHALATION: MAY CAUSE NASAL DRYNESS, IRRITATION AND

**OBSTRUCTION** 

# **EMERGENCY FIRST AID PROCEDURES**

INGESTION: REMOVE TO FRESH AIR. GET MEDICAL

ATTENTION, IF DIFFICULTY IN BREATHING

**OCCURS** 

EYE CONTACT: N/A

EYE CONTACT: WASH WITH WATER, IF IRRITATION DEVELOPS

**GET MEDICAL ATTENTION** 

SKIN CONTACT: IF BURNED BY CONTACT WITH MOLTEN

MATERIAL, COOL QUICKLY AND GET MEDICAL

**ATTENTION** 

NOTE TO PHYSICIAN: BURNS SHOULD BE TREATED AS THERMAL BURNS. PLASTIC WILL COME OFF AS HEALING OCCURS.

#### SPILL AND LEAK PROCEDURES

REMOVAL AND CLEAN UP AND INCINERATE OR BURY

DISPOSAL ACCORDING TO FEDERAL, STATE AND LOCAL

**REGULATIONS** 

### **SPECIAL PRECAUTIONS**

IN ACCORDANCE WITH GOOD INDUSTRIAL PRACTICES, HANDLE WITH CARE, AVOID CONTACT WITH OXIDIZING MATERIALS AND PROVIDE VENTILATION.

The information and data herein are believed to be accurate and have been compiled from sources believed to be reliable. There is no warranty of any kind, express or implied, concerning the accuracy or completeness of the information and data herein.